



大连星镁矿业有限公司  
STAR GRACE MINING CO., LTD.

Add: 29-67.No.929, Xinnan Road, Shahekou District, Dalian, Liaoning, China

**CERTIFICATE OF ANALYSIS**

**PRODUCT :** DICHLOROMETHANE (METHYLENE CHLORIDE)

THIS IS CERTIFY THAT WE, THE UNDERSIGNED HAVE INSPECTED THE QUALITY OF THE  
ABOVE MENTIONED GOODS AND FOUND THE RESULT OF INSPECTION AS FOLLOWS:

ITEMS	SPECIFICATIONS	RESULTS
Purity	$\geq 99.95\%$	99.99%
Water Content	$\leq 0.010\%$	0.008%
Residue on evaporation	$\leq 0.0015\%$	0.0005%
Acidity(HCL)	$\leq 0.0004\%$	0.0004%
Chroma(APHA)	$\leq 10$	5
Appearance	Clear	Clear
Form	Liquid	Liquid

**QUALITY CONTROL DEPT. MANAGER:** L. Mai

STAR GRACE MINING CO., LTD.  
大连星镁矿业有限公司

Wang Xiu Ling